Chemical Engineering 378

Science of Materials Engineering

Lecture 15 Failure and Fractures




Spiritual Thought

Moroni 7:48


48. Wherefore, my beloved brethren, pray unto the Father with all the energy of heart, that ye may be filled with this love, which he hath bestowed upon all who are true followers of his Son, Jesus Christ; that ye may become the BYSONS OF GOd...


Materials Roadmap



Strain Hardening

 Strain Hardening: The process by which ductile metal becomes harder as it is plasticly deformed.







Strain Hardening

Figure 7.5 (*a*) Two edge dislocations of the same sign and lying on the same slip plane exert a repulsive force on each other; *C* and *T* denote compression and tensile regions, respectively. (*b*) Edge dislocations of opposite sign and lying on the same slip plane exert an attractive force on each other. Upon meeting, they annihilate each other and leave a region of perfect crystal.

(Adapted from H. W. Hayden, W. G. Moffatt, and J. Wulff, *The Structure and Properties of Materials*, Vol. III, *Mechanical Behavior*, John Wiley & Sons, 1965. Reproduced with permission of Kathy Hayden.)

FOUNDED BYU





Strain Hardening (cont.) Dislocation Density and Cold Working

Dislocation density =

total dislocation length unit volume

- Dislocation density in undeformed metal

 \rightarrow 10⁵-10⁶ mm⁻²


- Dislocation density increases with increasing deformation
- Dislocation density in deformed (cold-worked) metal
 - \rightarrow 10⁹-10¹⁰ mm⁻²



Affect of Cold Work on Mechanical Properties


Example Problem:

Compute the yield and tensile strengths, and ductility for a cylindrical Cu specimen that has been cold worked by reducing its diameter from 15.2 mm to 12.2 mm.





Example Problem (cont.)





Example Problem (cont.)

Yield and tensile strength, and ductility (%EL) are determined graphically as shown below for %CW = 35.6%





Fig. 7.19, Callister & Rethwisch 10e. [Adapted from Metals Handbook: Properties and Selection: Irons and Steels, Vol. 1, 9th edition, B. Bardes (Editor), 1978; and Metals Handbook: Properties and Selection: Nonferrous Alloys and Pure Metals, Vol. 2, 9th edition, H. Baker (Managing Editor), 1979. Reproduced by permission of ASM International, Materials Park, OH.]

Heat Treatment of Cold-Worked Metal Alloys

- Heat treating cold worked metals brings about changes in structure and properties
- As a result, effects of cold work are nullified!
- This type of heat treatment sometimes termed "annealing"
- 1 hour treatment at T_{anneal} decreases tensile strength & increases %EL




Three Annealing stages:

- 1. Recovery (100-200° C)
- 2. Recrystallization (200-500°C)
- 3. Grain Growth (> 500° C)

Fig. 7.22, *Callister & Rethwisch 10e.* (Adapted from G. Sachs and K. R. Van Horn, *Practical Metallurgy, Applied Metallurgy and the Industrial Processing of Ferrous and Nonferrous Metals and Alloys*, 1940. Reproduced by permission of ASM International, Materials Park, OH.)

Recovery


During recovery – reduction in disl. density – annihilation of disl.






Recrystallization

- New grains form that:
 - -- have low dislocation densities
 - -- are small in size
 - -- consume and replace parent cold-worked grains.





Adapted from Fig. 7.21 (a),(c), Callister & Rethwisch 10e. (Photomicrographs courtesy of J.E. Burke, General Electric Company.)




BYU

After 4 sec. at 580° C

Recrystallization (cont.)

All grains in cold-worked material have been consumed/replaced.



After 8 sec. at 580° C

Adapted from Fig. 7.21 (d), *Callister* & *Rethwisch 10e.* (Photomicrographs courtesy of J.E. Burke, General Electric Company.)



 T_R = recrystallization temperature = temperature at which recrystallization just reaches completion in 1 h.

$$0.3T_m < T_R < 0.6T_m$$


For a specific metal/alloy, T_R depends on:


- %CW -- T_R decreases with increasing %CW
- Purity of metal -- T_R decreases with increasing purity



Grain Growth

- Grain growth occurs as heat treatment continues.
 - -- Average grain size increases
 - -- Small grains shrink (and ultimately disappear)
 - -- Large grains continue to grow





Adapted from Fig. 9.21 (d),(e), *Callister* & *Rethwisch 10e.* (Photomicrographs courtesy of J.E. Burke, General Electric Company.)




After 8 sec. at 580° C

After 15 min. at 580° C


Grain Growth (cont.)

• Empirical relationship—dependence of average grain size (*d*) on heat treating time (*t*):





Recovery, Recrystallization, & Grain Growth




BYU

T_R = recrystallization temperature

annealing time = 1 h

Fig. 7.22, Callister & Rethwisch 10e. (Adapted from G. Sachs and K. R. Van Horn, *Practical Metallurgy, Applied Metallurgy and the Industrial Processing of Ferrous and Nonferrous Metals and Alloys*, 1940. Reproduced by permission of ASM International, Materials Park, OH.)


Grain Size Effects Strength





Material Property Constants

Fracture Profiles





Fracture Surface Photographs





cup-and-cone fracture - moderately ductile

brittle fracture - totally brittle - flat surfaces

Fig. 8.3, Callister & Rethwisch 10e.




Examples of Ductile and Brittle Fracture of Pipes

• Ductile fracture:

-- one piece


-- large deformation



Brittle fracture:


-- many pieces-- small deformations

Figures from V.J. Colangelo and F.A. Heiser, *Analysis of Metallurgical Failures* (2nd ed.), Fig. 4.1(a) and (b), p. 66 John Wiley and Sons, Inc., 1987. Used with permission.





Stages of Moderately Ductile Failure



From V.J. Colangelo and F.A. Heiser, *Analysis of Metallurgical Failures* (2nd ed.), Fig. 11.28, p. 294, John Wiley and Sons, Inc., 1987. (Orig. source: P. Thornton, *J. Mater. Sci.*, Vol. 6, 1971, pp. 347-56.)

serve as void

nucleation

BYU Sites.

Fracture surface of tire cord wire loaded tension. Courtesy of F. Roehrig, CC Technologies, Dublin, OH. Used with permission.

cup and cone fracture surface

Brittle Failure Surface Photographs

- Brittle fracture surface displays V-shaped, chevron markings
- V features point to the crack initiation site







Fig. 8.5(a), *Callister & Rethwisch 10e*. [From R. W. Hertzberg, *Deformation and Fracture Mechanics of Engineering Materials*, 3rd edition. Copyright © 1989 by John Wiley & Sons, New York. Reprinted by permission of John Wiley & Sons, Inc. Photograph courtesy of Roger Slutter, Lehigh University.]

Photographs of Brittle Fracture Surfaces

 Intergranular crack propagation (between grains)




304 S. Steel (metal)

Reprinted w/permission from "Metals Handbook", 9th ed, Fig. 633, p. 650. Copyright 1985, ASM International, Materials Park, OH. (Micrograph by J.R. Keiser and A.R. Olsen, Oak Ridge National Lab.)



• Transgranular crack propagation (through grains)



316 S. Steel (metal)


Reprinted w/ permission from "Metals Handbook", 9th ed, Fig. 650, p. 357. Copyright 1985, ASM International, Materials Park, OH. (Micrograph by D.R. Diercks, Argonne National Lab.)

Principles of Fracture Mechanics

- Fracture occurs as result of crack propagation
- Measured fracture strengths of most materials much lower than predicted by theory
 - microscopic flaws (cracks) always exist in materials
 - magnitude of applied tensile stress amplified at the tips of these cracks



Fracture Mechanics (cont.)



 $\sigma_m = 2\sigma_o\left(\frac{a}{\rho_t}\right)$


 ρ_t = radius of curvature σ_o = applied stress σ_m = stress at crack tip

Fig. 8.8(a), Callister & Rethwisch 10e.

Fracture Mechanics (cont.)

- Stress Concentration at Crack Tip
 - K_t = stress concentration factor

$$K_t = \frac{\sigma_m}{\sigma_o}$$




Adapted from Fig. 8.8(b), *Callister & Rethwisch 10e.*



Fracture Mechanics (cont.)


Avoid sharp corners!





Crack Propagation

- Stress concentration higher for sharp cracks propagate at lower stresses than cracks with blunt tips
- For ductile materials—plastic deformation at crack tip when stress reaches yield strength—tip blunted lowers stress conc.





Criterion for Crack Propagation

Critical stress for crack propagation (σ_c) of brittle materials

$$\sigma_{c} = \left(\frac{2E\gamma_{s}}{\pi a}\right)^{1/2}$$

where

 $\Box \sigma_c$ = crack-tip stress

- E = modulus of elasticity
- $-\gamma_s$ = specific surface energy
- -a = one half length of internal crack

For ductile materials replace γ_s with $\gamma_s + \gamma_p$ where γ_p is plastic deformation energy

- materials have numerous cracks with different lengths and orientations
- crack propagation (and fracture) occurs when $\sigma_m > \sigma_c$ for crack with lowest σ_c



Largest, most highly stressed cracks grow first!