

Chemical Engineering 378

Science of Materials Engineering

Lecture 24

Various Metals, Processing



Spiritual Thought


“I urge you to not take counsel of your fears. I hope you will not say, “I’m not smart enough to study chemical engineering; hence, I’ll study something less strenuous.” “I can’t apply myself sufficiently well to study this difficult subject or in this comprehensive field; hence, I’ll choose the easier way.” I plead with you to choose the hard way and tax your talents. Our Heavenly Father will make you equal to your tasks. If one should stumble, if one should take a course and get less than the “A” grade desired, I hope such a one will not let it become a discouraging thing to him. I hope that he will rise and try again.”

President Thomas S. Monson




Materials Roadmap

Materials Science




Classification of Metal Alloys



Adapted from Fig. 11.1, *Callister & Rethwisch 10e*.


Fig. 9.24, *Callister & Rethwisch 10e*.
[Adapted from Binary Alloy Phase Diagrams, 2nd edition, Vol. 1, T. B. Massalski (Editor-in-Chief), 1990. Reprinted by permission of ASM International, Materials Park, OH.]

Steels




Based on data provided in Tables 11.1(b), 11.3, and 11.4, *Callister & Rethwisch 10e*.

Refinement of Steel from Ore





BLAST FURNACE



heat generation



reduction of iron ore to metal



purification



Ferrous Alloys

Iron-based alloys

- Steels
- Cast Irons

Nomenclature for steels (AISI/SAE)

10xx Plain Carbon Steels

11xx Plain Carbon Steels (resulfurized for machinability)

15xx Mn (1.00 - 1.65%)

40xx Mo (0.20 ~ 0.30%)

43xx Ni (1.65 - 2.00%), Cr (0.40 - 0.90%), Mo (0.20 - 0.30%)

44xx Mo (0.5%)

where xx is wt% C x 100

example: 1060 steel – plain carbon steel with 0.60 wt% C

Stainless Steel >11% Cr



Cast Irons

- **Ferrous alloys** with $> 2.1 \text{ wt\% C}$
 - more commonly 3 - 4.5 wt% C
- Low melting – relatively easy to cast
- Generally brittle
- Cementite decomposes to ferrite + graphite
$$\text{Fe}_3\text{C} \rightarrow 3 \text{ Fe } (\alpha) + \text{C (graphite)}$$
 - generally a slow process



Fe-C True Equilibrium Diagram

Graphite formation promoted by

- Si > 1 wt%
- slow cooling




Fig. 11.2, Callister & Rethwisch 10e.
[Adapted from *Binary Alloy Phase Diagrams*,
T. B. Massalski (Editor-in-Chief), 1990.
Reprinted by permission of ASM International,
Materials Park, OH.]


Types of Cast Iron

Gray iron

- graphite flakes
- weak & brittle in tension
- stronger in compression
- excellent vibrational dampening
- wear resistant


Figs. 11.3(a) & (b),
*Callister &
Rethwisch 10e.*

[Courtesy of C. H.
Brady and L. C. Smith,
National Bureau of
Standards, Washington,
DC (now the National
Institute of Standards
and Technology,
Gaithersburg, MD)]



Ductile iron

- add Mg and/or Ce
- graphite as nodules not flakes
- matrix often pearlite – stronger but less ductile



Types of Cast Iron (cont.)

White iron

- < 1 wt% Si
- pearlite + cementite
- very hard and brittle


Figs. 11.3(c) & (d),
*Callister &
Rethwisch 10e.*



Courtesy of Amcast Industrial Corporation

Malleable iron

- heat treat white iron at $800-900^{\circ}\text{C}$
- graphite in rosettes
- reasonably strong and ductile



Reprinted with permission of the
Iron Castings Society, Des Plaines, IL

Types of Cast Iron (cont.)

Compacted graphite iron

- relatively high thermal conductivity
- good resistance to thermal shock
- lower oxidation at elevated temperatures





Fig. 11.3(e), *Callister & Rethwisch 10e*.

Production of Cast Irons


Fig.11.5, *Callister & Rethwisch 10e*.

(Adapted from W. G. Moffatt, G. W. Pearsall, and J. Wulff, *The Structure and Properties of Materials*, Vol. I, Structure, p. 195. Copyright © 1964 by John Wiley & Sons, New York. Reprinted by permission of John Wiley & Sons, Inc.)




Reheat: hold at
 $\sim 700^\circ\text{C}$ for 30 + h

Fast cool	Slow cool
$P + G_r$	$\alpha + G_r$



Pearlitic malleable



Ferritic malleable

Limitations of Ferrous Alloys

- 1) Relatively high densities
- 2) Relatively low electrical conductivities
- 3) Generally poor corrosion resistance



Nonferrous Alloys

• Cu Alloys

Brass: Zn is subst. impurity (costume jewelry, coins, corrosion resistant)

Bronze: Sn, Al, Si, Ni are subst. impurities (bushings, landing gear)

Cu-Be: precip. hardened for strength

• Ti Alloys

-relatively low ρ : 4.5 g/cm³

vs 7.9 for steel

-reactive at high T 's
-space applic.

• Al Alloys

-low ρ : 2.7 g/cm³

-Cu, Mg, Si, Mn, Zn additions
-solid sol. or precip.

strengthened (struct. aircraft parts & packaging)

• Mg Alloys

-very low ρ : 1.7 g/cm³

-ignites easily
-aircraft, missiles

• Refractory metals

-high melting T 's
-Nb, Mo, W, Ta

NonFerrous Alloys

• Noble metals

-Ag, Au, Pt
-oxid./corr. resistant



Metal Fabrication

- How do we fabricate metals?
 - Blacksmith - hammer (forged)
 - Cast molten metal into mold
- Forming Operations
 - Rough stock formed to final shape

Hot working

vs.

Cold working

- Deformation temperature high enough for recrystallization
- Large deformations

- Deformation below recrystallization temperature
- Strain hardening occurs
- Small deformations




Metal Fabrication Methods (i)

FORMING


CASTING

MISCELLANEOUS


- **Forging (Hammering; Stamping)** (wrenches, crankshafts)
- **Rolling (Hot or Cold Rolling)** (I-beams, rails, sheet & plate)



- **Drawing** (rods, wire, tubing)




die must be well lubricated & clean




Adapted from
Fig. 11.9,
Callister &
Rethwisch 10e.

- **Extrusion** (rods, tubing)



ductile metals, e.g. Cu, Al (hot)


Metal Fabrication Methods (ii)



- **Casting**- mold is filled with molten metal
 - metal melted in furnace, perhaps alloying elements added, then **cast** in a mold
 - common and inexpensive
 - gives good production of shapes
 - weaker products, internal defects
 - good option for brittle materials




Metal Fabrication Methods (iii)




- **Sand Casting**

(large parts, e.g.,
auto engine blocks)




- What material will withstand $T > 1600^{\circ} \text{C}$ and is inexpensive and easy to mold?
- Answer: sand!!!
- To create mold, pack sand around form (pattern) of desired shape


Metal Fabrication Methods (iv)



- **Investment Casting**
(low volume, complex shapes
e.g., jewelry, turbine blades)
- **Stage I** — Mold formed by pouring plaster of paris around wax pattern. Plaster allowed to harden.
- **Stage II** — Wax is melted and then poured from mold—hollow mold cavity remains.
- **Stage III** — Molten metal is poured into mold and allowed to solidify.




Metal Fabrication Methods (v)




- **Die Casting**

- high volume
- for alloys having low melting temperatures



- **Continuous Casting**

- simple shapes
(e.g., rectangular slabs, cylinders)




Metal Fabrication Methods (vi)

FORMING

CASTING

MISCELLANEOUS

- **Powder Metallurgy**
(metals w/low ductilities)



- **Welding**
(when fabrication of one large part is impractical)





Fig. 11.10, Callister & Rethwisch 10e.
[From *Iron Castings Handbook*, C.F. Walton and T.J. Opar (Ed.), Iron Castings Society, Des Plaines, IL, 1981.]

- **Heat-affected zone:**
(region in which the microstructure has been changed).

Thermal Processing of Metals

Annealing: Heat to T_{anneal} , then cool slowly.



Heat Treatment Temperature-Time Paths

a) Full Annealing

b) Quenching

c) Tempering
(Tempered
Martensite)




Fig. 10.25, *Callister & Rethwisch 10e*.
[Adapted from H. Boyer (Editor), *Atlas of Isothermal Transformation and Cooling Transformation Diagrams*, 1977. Reproduced by permission of ASM International, Materials Park, OH.]

Precipitation Hardening

- Particles impede dislocation motion.

- Ex: Al-Cu system

- Procedure:

- Pt A: solution heat treat (get α solid solution)
- Pt B: quench to room temp. (retain α solid solution)
- Pt C: reheat to nucleate small θ particles within α phase.

- Other alloys that precipitation harden:

- Cu-Be
- Cu-Sn
- Mg-Al





Fig. 11.29, Callister & Rethwisch 10e.
(Adapted from J.L. Murray, *International Metals Review* 30, p.5, 1985. Reprinted by permission of ASM International.)



Adapted from Fig. 11.27, Callister & Rethwisch 10e.

Influence of Precipitation Heat Treatment on TS , % EL

- 2014 Al Alloy:
- Maxima on TS curves.
- Increasing T accelerates process.
- Minima on % EL curves.





Fig. 11.32, Callister & Rethwisch 10e. [Adapted from *Metals Handbook: Properties and Selection: Nonferrous Alloys and Pure Metals*, Vol. 2, 9th ed., H. Baker (Managing Ed.), 1979. Reproduced by permission of ASM International, Materials Park, OH.]

Hardenability -- Steels

- Hardenability – measure of the ability to form martensite
- Jominy end quench test used to measure hardenability.




Fig. 11.15, Callister & Rethwisch 10e.
(Adapted from A.G. Guy, *Essentials of Materials Science*, McGraw-Hill Book Company, New York, 1978.)

- Plot hardness versus distance from the quenched end.




Fig. 11.16, Callister & Rethwisch 10e.

Reason Why Hardness Changes with Distance

- The cooling rate decreases with distance from quenched end.





Fig. 11.17, *Callister & Rethwisch 10e*.
[Adapted from H. Boyer (Ed.), *Atlas of Isothermal Transformation and Cooling Transformation Diagrams*, 1977. Reproduced by permission of ASM International, Materials Park, OH.]


Hardenability vs Alloy Composition

- Hardenability curves for five alloys each with, $C = 0.4 \text{ wt\% C}$

Fig. 11.18, *Callister & Rethwisch 10e*.
(Adapted from figure furnished courtesy Republic Steel Corporation.)



- "Alloy Steels"
(4140, 4340, 5140, 8640)
 - contain Ni, Cr, Mo (0.2 to 2 wt%)
 - these elements shift the "nose" to longer times (from A to B)
 - martensite is easier to form



Influences of Quenching Medium & Specimen Geometry

- Effect of quenching medium:

Medium	Severity of Quench	Hardness
air	low	low
oil	moderate	moderate
water	high	high

- Effect of specimen geometry:

When surface area-to-volume ratio increases:

- cooling rate throughout interior increases
- hardness throughout interior increases

